




Rear View





Left Side Right Side Add-ons Missing Loose/broken/delaminated Previous repair Spindles not original to desk Inscriptions Damage/wear/hole Replaced piece

Top













Bottom


Bottom





Drawer Front, Outer Surface


Rear Surface of Drawer Front













Inside Surface of Left Drawer Side


Inside Surface of Right Drawer Side




Rear Surface of Drawer Back


Front Surface of Drawer Back















Upper Surface of Drawer Bottom

Lower Surface of Drawer Bottom



Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Missing Missing

Spindles not original to desk

Add-ons

Inscriptions